



## **Solid Surface Cleaning Instructions**

Routine cleaning can be accomplished with the use of a wet cloth.

To bring back the shine of your counter apply a little Soft Scrub with a sponge, then rinse clean with a wet rag.

Do not apply any type of polish as they will wear off in heavily used areas and give your counters an uneven look. They will also be an attractant for dirt.

For treating superficial scratches that may occur, use the Gray Scotch-Brite pad. Use circular strokes with firm, but moderate pressure and your surface will be renewed to its original sheen and beauty. Your countertop naturally takes on different finishes in areas of heavy use. Because of this refinishing the whole counter in this method will provide you better results.